L Number	Hits	Search Text	DB	Time stamp
1	271	(seat\$5 near4 (tens\$5 stress strai force load) near3	USPAT;	2004/09/15 15:06
		(test\$5 detect\$5 sens\$5 estimat\$5 evalut\$5	EPO; JPO	
	1	determin\$5 measur\$5 transducer cell meter gauge		
	1	monitor\$5 )).clm.		
2	31	((seat\$5 near4 (tens\$5 stress strai force load)	USPAT;	2004/09/15 16:10
	+	near3 (test\$5 detect\$5 sens\$5 estimat\$5 evalut\$5	EPO; JPO	
	•	determin\$5 measur\$5 transducer cell meter gauge		
	}	monitor\$5 )).clm.) and (strain near3 gauge).clm.		
3	5	(((seat\$5 near4 (tens\$5 stress strai force load)	USPAT;	2004/09/15 15:27
	-	near3 (test\$5 detect\$5 sens\$5 estimat\$5 evalut\$5	EPO; JPO	
	1	determin\$5 measur\$5 transducer cell meter gauge		
		monitor\$5 )).clm.) and (strain near3 gauge).clm.)		
	1	and (cpu computer process\$5).clm.		
13	81		USPAT;	2004/09/15 16:10
		strain force load) near3 (test\$5 detect\$5 sens\$5	EPO; JPO	200-1700710 10:10
		estimat\$5 evalut\$5 determin\$5 measur\$5	2. 0, 0. 0	
		transducer cell meter gauge monitor\$5 )).clm.		
15	2	((((seatbelt (seat near2 belt)) near4 (tens\$5 stress	USPAT;	2004/09/15 15:39
	_	strain force load) near3 (test\$5 detect\$5 sens\$5	EPO; JPO	2004/00/10 10:00
		estimat\$5 evalut\$5 determin\$5 measur\$5	21 0, 01 0	
		transducer cell meter gauge monitor\$5 )).clm.) and		
		(strain near3 gauge).clm.) and (cpu computer		
		\$6process\$5).clm.		
16	5	((((seatbelt (seat near2 belt)) near4 (tens\$5 stress	USPAT;	2004/09/15 16:13
		strain force load) near3 (test\$5 detect\$5 sens\$5	EPO; JPO	2004/03/13 10:10
		estimat\$5 evalut\$5 determin\$5 measur\$5	2.0,0.0	1
		transducer cell meter gauge monitor\$5 )).clm.) and		
	İ	(strain near3 gauge).clm.) and (cpu computer		
		\$6process\$5)		
17	1	("6231076").PN.	USPAT;	2004/09/15 15:45
	'	( 0201070 ).114.	EPO; JPO	2004/05/10 10:40
14	11	(((seatbelt (seat near2 belt)) near4 (tens\$5 stress	USPAT;	2004/09/15 15:49
	1	strain force load) near3 (test\$5 detect\$5 sens\$5	EPO; JPO	200 1/00/10 10:10
		estimat\$5 evalut\$5 determin\$5 measur\$5	2. 0, 0. 0	
	}	transducer cell meter gauge monitor\$5 )).clm.) and		
		(strain near3 gauge).clm.		
18	17		USPAT;	2004/09/15 15:49
		strain force load) near3 (test\$5 detect\$5 sens\$5	EPO; JPO	
		estimat\$5 evalut\$5 determin\$5 measur\$5		
		transducer cell meter gauge monitor\$5 )).clm.) and	i	
		(strain near3 gauge)		
19	326		USPAT;	2004/09/15 16:11
		(test\$5 detect\$5 sens\$5 estimat\$5 evalut\$5	EPO; JPO	
		determin\$5 measur\$5 transducer cell meter gauge	,	
		monitor\$5 )).clm.	İ	
20	21	(((belt) near4 (tens\$5 stress strain force load)	USPAT;	2004/09/15 16:12
	]	near3 (test\$5 detect\$5 sens\$5 estimat\$5 evalut\$5	EPO; JPO	
		determin\$5 measur\$5 transducer cell meter gauge		
		monitor\$5 )).clm.) and (strain near3 gauge).clm.		
21	1254078	"21" and (cpu computer \$6process\$5)	USPAT;	2004/09/15 17:27
		_ · · · · · · · · · · · · · · · · · · ·	EPO; JPO	
22	13	((((belt) near4 (tens\$5 stress strain force load)	USPAT:	2004/09/15 17:29
_ <del>_</del>	1	near3 (test\$5 detect\$5 sens\$5 estimat\$5 evalut\$5	EPO; JPO	
		determin\$5 measur\$5 transducer cell meter gauge		
	- 4	monitor\$5 )).clm.) and (strain near3 gauge).clm.)		
		and (cpu computer \$6process\$5)		